

CLASSIFIED MESSAGE

ROUTING

ORIG
UNIT
EXT
DATE : 28 JAN 1963

S-E-C-R-E-T

1	COMMO/OSA	4	DD/R
2	DAD/OSA	5	DD/P
3	AD/OSA	6	C/FE

C/FE
ADMIN/OSA
KSB/OSA
C/PS
RB/OSA

TO :
FROM: DIRECTOR
CONF: OSA (1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16)
INFO: S/C (17)

P R O C E D U R E S		DEFERRED	PRIORITY	INITIALS
	IX	ROUTINE	OPERATIONAL IMMEDIATE	INITIALS

OUT42883

DTG 1655Z 28 JAN 63

TO: INFO CITE 2337
COMMO

FOLLOWING IS TECH FEEDBACK MISSION 3215:

1. P BAND NOISY FROM "AC OFF". L BAND AND X BAND QUIET. S BAND HAD REGULAR NOISE, PROBABLY MOTOR ABOARD PLANE.
2. TAPE BOTH RECORDERS RAN OUT EARLY. REQUEST IN FUTURE IF TAPE CUT OFF BEFORE "AC OFF", THIS TIME BE INCLUDED IN DATA SHEETS.
3. ANALYST REQUESTS WIRING BE CHECKED ASSURE X AND S BAND SWITCHING RIGHT AND LEFT PROPERLY AND TOGETHER.

END OF MESSAGE

25 YEAR RE-REVIEW

CHIEF, OSA/COMMO

COORDINATING OFFICERS

GROUP 1 - Excluded from
automatic downgrading
and declassification.

RELEASING OFFICER

S-E-C-R-E-T

AUTHENTICATING OFFICER

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.